North	Decatur	Road
Ouar	ntity Ove	rrun

	Quantity Overrun	
Item No.	Description	Reasoning
		It was discovered early on that the plans omitted GAB
	Graded Aggr Base CRS,	underneath the header curb, so enough quantity was not
210-0100	INCL MATL	set up.
	Recycled Asph Conc	
402-3130	12.5mm	Overrun by 2.59 tons due to field conditions.
		Not enough quantity was set up in the plans for the
441-0740	Concrete Median, 4IN	raised concrete medians.
		The plans showed a proposed driveway and valley gutter
		at STA 312+00 LT. A pay item was set up for Conc Valley
		Gutter 8 IN but not for the driveway portion. The overrun
	Concrete Valley Gutter, 8	was caused by the driveway concrete being added with
441-4030	IN	the valley gutter quantity.
	Conc Header Curb, 6 IN,	Additional concrete header curb was used due to field
441-5002	TP 2	conditions to provide clean tie ins to existing curbs.
		Overrun by 21 SY to provide for clean tie ins and to
		replace damaged sidewalk at the tie ins to provide a
441-0104	Conc Sidewalk 4 IN	clean transition.
		The ADA ramp at STA 318+20 RT was extended per
		request of PM to provide adequate transition space to be
441-0108	Conc Sidewalk 8 IN	ADA compliant.
		Per county request the drop inlets at the Springdale
	Reconstr Drop Inlet,	intersection were reconstructed twice to change the
668-3010	Group 1	grate.
	Electrical Service Point	
	Assembly, Aerial Service	An additional service point was needed to service the
939-5010	Point	electrical items on the project.