



**DEPARTMENT OF PURCHASING AND CONTRACTING
BID TABULATION**

ITB No. 20-101270

ITB Name: HELICOPTER MAINTENANCE AND REPAIR SERVICE
(Annual Contract With 2 Options to Renew)

Bid Opening: September 3, 2020
Price Schedule Opening: September 17, 2020
Procurement Agent: Michele L. Smith

		VENDOR:		ROTOR RESOURCES, LLC	
Line No.	Description	Estimated # of Units	Unit of Measure (UOM)	Unit Price	Total Price
1.	Labor rate / Emergency Service hourly rate (Labor rate shall include consumables such as rags, nuts, bolts, tie wraps, grease, sealants, cleaners, and/or solvents.)	2	Per Hour	\$ 157.50	\$ 315.00
2.	100 hour inspection (flat rate) for AS350-B2	2	Flat Rate	\$ 500.00	\$ 1,000.00
3.	150 hour inspection (flat rate) for AS350-B2	2	Flat Rate	\$ 1,000.00	\$ 2,000.00
4.	150 hour oil filter change for AS350-B2	2	Each	\$ 110.00	\$ 220.00
5.	Annual Inspection for AS350-B2	2	Each	\$ 950.00	\$ 1,900.00
6.	600 hour inspection or biennial inspection for AS350-B2	2	Each	\$ 5,000.00	\$ 10,000.00
7.	1200 hour inspection or 48 months for AS350-B2	2	Each	\$ 1,350.00	\$ 2,700.00
8.	Labor rate, Inspections outside the Manufacturer's requirements, such as: ICA's (instructions for continued airworthiness) and AD's (airworthiness directives), not already listed above. Labor rate shall include consumables such as rags, nuts, bolts, tie wraps, grease, sealants, cleaners, and/or solvents.	2	Per Hour	\$ 110.00	\$ 220.00
9.	If another Helicopter is added, would all prices be the same? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Difference in price(s), if any:				
10.	Bidder shall state discount from Parts List for special parts requirements. (Do not state the discount in the form of cost-plus. Stating the discount in the form of cost-plus fails to tell the County the percentage that it will save.)	0%			
Number of Bids Received: 2					
LSBE Participation Benchmark/GFE:					GFE Approved by CPO
Attendance at the Mandatory LSBE Meeting (Yes/No):					Yes
Separate Sealed Price Schedule (Yes/No):					Yes
NOTES/DETAIL JUSTIFICATION:					
Recommend award to the lowest, responsive and responsible bidder: Rotor Resources, LLC, 169 Commodore Path, Hiram, GA 30141					
Gardner Aviation Specialist, Inc. DBA Precision Aircraft Services, Peachtree City, GA, was deemed non-responsive for failure to meet the County's LSBE participation benchmark or demonstrate Good Faith Effort and failure to complete and return the entire solicitation as required on page 3, in the solicitation.					